INDEPENDENT

BATTERY CERTIFICATE



CERTIFICATE NUMBER: E146A725-806F-4903-BB99-43A73EF5AF3A

VEHICLE

RESULTS

BRAND: BMW

WLTP RANGE

MODEL: X3 xDrive 30e - 22,7 kWh


MILEAGE:

VIN: WBA65GP03SN323603

DATE AND TIME: 11.09.2025, 11:23:23

EXECUTED BY: 135024 - Bergwerff

Automotive B.V



PATING

BENCHMARKING How does your vehicle

compare to comparable vehicles?

below average

average

above average

Battery Management System (BMS) - analysis failed

Battery Sensor - analysis failed

Battery Measurements - analysis failed

Battery Cell Voltages - analysis failed

Vehicle Communication - warning detected



ALUATION

INCONCLUSIVE - BATTERY HEALTH UNDETERMINED

The detailed battery diagnosis with the AVILOO FLASH test failed because not all requirements were met during the measurement. For Details scan the QR code.

For assistance, please contact AVILOO Customer Management.

horas Reiser

Dr. Marcus Berger, CEO



Voltage Sensor

Current Sensor

Temperature Sensors

Cell Voltage Sensors

WLTP Typical

Current:

New:

BMS State of Charge (SoC)*: --%

SoC calculation accuracy:

BMS State of Health (SoH)*: --%

SoH calculation accuracy:

AVILOO Box connected. 11:23:19

FLASH Test started.

Vehicle detected.

Starting data acquisition.

Finished data acquisition.

Min Max Delta Status

Battery Temperature --°C ---°C ---°C

Cell-Voltage ---V ---W

Pack Voltage ---V

Average Current ---A

MESSAGES

EXECUTION PROTOCOL

Analysis failed because not all necessary signals were received during data acquisition. Please repeat the test. If the problem persists, please contact AVLOO Customer Management.

SENSORS

MEASUREMENTS



*The values shown here were not calculated by AVILOO but correspond to the values read out from the battery management system (BMS) and were calculated by the manufacturer. AVILOO therefore assumes no liability for their accuracy.

DISCLAIMER: The test result includes the currently calculated state of health (SoH) of the drive battery. The determination is based on data provided by the vehicle. These are evaluated by AVILOOs algorithms using statistical and analytical models. Manipulation of the data in the control unit leads to an incorrect result. The indicated SoH has a technically induced fluctuation range (deviation) of no more than 3% in at least 95% of reference measurements. It should be noted that this tolerance applies to the SoH determination at the cell level and not to the SoH of the entire battery. This is because the state of charge of individual cells may vary, which can negatively affect the current SoH of the battery. However, this can be compensated by the Battery Managament System (BMS) or during a calibration. The result reflects the condition of the battery at the time of the test. No conclusions can be drawn about the future state of health of the battery from this. Statements about mechanical damage or external influences are not part of this diagnosis.